





# MACH3

## MKX




184 x127x30 mm

**PRADO**  
AUTOMAÇÃO INDUSTRIAL



schematic diagram






### Features:


- ★ Fully supporting all Mach3 versions
- ★ Full support for USB hot-swappable, the card is Monitoring USB connection status at any time.
- ★ Supports Up 6-axis
- ★ Maximum step-pulse frequency is 2000KHz
- ★ Status indicator LED can be useful to show the USB connection, and working status by flashing.
- ★ 16 general-purpose input, 8 output
- ★ has speed function, the spindle actual speed Mach3 interface in real-time display
- ★ all IO-port isolation, interference, stable performance
- ★ Support spindle speed feedback
- ★ Support save data when power off

## Simple connection description

### Application Connection Diagram




# English Introduction Signal Description



# English Introduction

## Wiring diagram shows

NOTE: If the inverter is turned on, the control card is not working properly because of interference caused by the inverter; Replace inverter.



## 第2部份：英文介绍/ English Introduction

### Electrical Characteristics

	Parameter Description	
axis output control:	Drive Current	Isolated open collector output; 5V, 20mA
	Drive	Pulse + direction output
	Output frequency	2000KHZ
	axes	MK3-M4:3-axis;MK4-M4:4-axis;MK6-M4:6-axis
	Isolation Voltage	3.5KV
Spindle inverter output: 3 types of output modes	Analog voltage output	0—10V
	PWM output	5V,1KHZ, Duty:0-100%
	Pulse+direction output	5V,15HZ to 4KHZ
8 IO output	Drive Current	Isolation:50mA, 25V
	Isolation Voltage	3.5KV
16 IO input	Input Current	Isolated inputs, 5 mA, maximum voltage 25V
	Isolation Voltage	3.5KV
USB interface	Complies with USB2.0 standard	

## 附件：接线图( Software installation)

## 软件安装 (Software installation)

- No.1:Install MACH3 software
- No.2: copy drive to the specified MACH3 directory see the disc information:..\English Manual\usb card driver\readme.txt
- No.3: See wiring diagram, which will control the card connection correctly
- No.4: Connect the control card and computer with the USB line.

To complete the above steps, you can open the MACH3 software, and use.



See print Manual: "MACH3 parameter setting", adjust the parameters such as pulse equivalent set

## (Annex 2:Wiring schematics )


MKX Wiring schematics

NO.1 : power input

power : 24V,0.5A


DC 0V\_GND  
DC 24V-INPUT

Work Current ; 0.5A




2.NO.2 Drive Interface : Supporting servo or stepping drive

## NO.3 Inverter Interface




MKX Wiring schematics


Spindle connected stepper or servo drives



NO.4 : Relay Interface : OUT2 to OUT7 Relay Interface



NO.5 : input Interface : 15 input port;In0 to In15.Active Low




---

---

New features


Break continue: when the control card suddenly power off, the control card chip automatically save the current G code line number. Control card plug-in display save the number of lines.



Wait until the control card is connected to the power supply next, load the G code program, click the power to continue to the break continue button, Mach3 software automatically from the last save the number of lines to start running.



Spindle speed feedback: spindle speed feedback through the sensor feedback to Input port "Speed-DEC" , and then display the RPM speed on the Mach3 software. Maximum support feedback inputPulse frequency 20KHZ.



USB anti interference: the new design of the independent USB data processor, to prevent the interference of USB communication, more stable and reliable. Suitable for plasma cutting and automatic welding and so on.

